


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/96 To (mo./yr.) 12/96
2. DOGM File Number (Mine No): M / 47 / 010
3. Mine Name: Bonanza Mines
4. Mineral(s) Mined (or permitted to mine): Gilsonite
5. Type of mine ☐ Surface Mine or ☒ Underground Mine
6. Legal Description (Location of Lands Affected):
1/4, 1/4, Section _____, Township _____, Range _____
1/4, 1/4, Section _____, Township _____, Range _____
1/4, 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: American Gilsonite Co.
8. Permanent Street Address: Mine Site
City, State, Zip: Bonanza, UT
Phone: 801-789-1921
9. Company Representative (or designated operator):
Name: Neldon Kunz
Title: Mine Supt.
Business Address: HC 73 Box 28
City, State, Zip: Vernal, UT 84078
Phone: 801-789-1921

☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 33,482 Tons

3. How much **additional acreage** was disturbed during the past year? 0
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
- _____
- _____
- _____
5. How much acreage was **reclaimed** during the past year? 5
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
- Nine shafts were capped with reinforced concrete
- and the areas regraded and cleaned up and reseeded.
- _____
- _____
7. What is the **total disturbed acreage** at years end? 103.2
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
- We expect to start one new mine shaft, which will
- disturb about 1 acre.
- _____
- _____

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information


1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Neldon Kunz

Title of Operator: Mine Supt.

Signature of Operator: 

Date: 1/22/97